

## 2016 Land Rover Range Rover Sport V6 3.0L

Inspected on: 18th January 2025

Top Quality Assurance

Serviced and Checked across 150+ points

✓ Passed

✓ Passed

✓ Passed

Exceeds RTA Standards

Guaranteed

## **Your Car Condition Report**

Doors condition		
Front left door	✓ Pas	sed
Front right door	✓ Pas	sed
Rear left door	✓ Pas	sed
Rear right door	✓ Pas	sed
Fenders Condition		
Left Fender	✓ Pas	sed
Right Fender	✓ Pas	sed
Quarter Panels Condition		
Left Quarter Panel	✓ Pas	sed
Right Quarter Panel	✓ Pas	sed
Front Bumper Condition		
Front Bumper	✓ Pas	sed
Rear Bumper Condition		
Rear Bumper	✓ Pas	sed
Hood Condition		
Hood	✓ Pas	sed
Trunk Condition		
Trunk	✓ Pas	sed
Trunk conditon		
Trunk	✓ Pas	sed
Roof Condition		
Roof	✓ Pas	sed

ngine	
Engine Body	✓ Passed
Engine Performance	✓ Passed
Engine Oil (Condition & Level)	✓ Passed
Exhaust System	✓ Passed
Radiator Condition	✓ Passed
Radiator Coolant	✓ Passed
uel System	
Fuel Tank	✓ Passed
ransmission Operation	
Gear Shifting	✓ Passed
	✓ Passed
Gear shift	
	✓ Passed
Gear shift  Drive Axle  4*4 Condition (If Applicable)	✓ Passed ✓ Passed

©Electricals, Controls & Lights

Keys

Master Key

Spare Key(s)

Door Locks

Dashboard

Child Safety Locking

Instrument Panel

Left A Pillar	✓ Passed
Right A Pillar	→ Passed Airbags Airbags
Left A to B Pillar Beading	✓ Passed Controls
Right A to B Pillar Beading	✓ Passed
Right A to B Pillar	✓ Passed Cruise Control
Left B Pillar	✓ Passed
Left B Pillar Trim	✓ Passed OBD Connector
Left B to C Pillar Beading	✓ Passed Music System
Right C Pillar Trim	✓ Passed Camera
Right B to C Pillar	✓ Passed Lights
Right B to C Pillar Beading	✓ Passed Headlight
Left C Pillar	✓ Passed Interior Lights
Running Board Condition	Tail Light Cluster
Left Running Board	✓ Passed Daylight Running Lights
Right Running Board	✓ Passed License Plate Light
Windshield Condition	Fog Lights
Front Windshield	✓ Passed Air Conditioning
Rear Windshield	✓ Passed AC Cooling
Structural Assessment	AC Switch
Chassis Condition	✓ Passed AC System Leaks
Apron	✓ Passed Center AC Vent
Boot Floor	✓ Passed Front Right AC Vent
Firewall Condition	✓ Passed Heater
Cowl Top	✓ Passed Rear Blower Switch
Head Light Support Condition	✓ Passed Rear Left AC Vent
Cowl Top	Parking Sensors
Cowl Top	✓ Passed
Dogr Vious Missor Condition	Rear Defogger ———————————————————————————————————
Rear View Mirror Condition  Left Hand Side Mirror	USB Charging Port  Passed
	Power/ Manual Windows
Left Side Mirror	· ·
Right Side Mirror	✓ Passed

Airbags	✓ P	assed
All 24gs	<u> </u>	
Controls	✓ P	assed
Cruise Control	✓ P	assed
Infotainment Display	✓ P	assed
OBD Connector	✓ P	assed
Music System	✓ P	assed
Camera	✓ P	assed
Lights		
Headlight	✓ P	assed
Interior Lights	✓ P	assed
Tail Light Cluster	✓ P	assed
Daylight Running Lights	✓ P	assed
License Plate Light	✓ P	assed
Fog Lights	✓ P	assed
Air Conditioning		
AC Cooling	✓ P	assed
AC Switch	✓ P	assed
AC System Leaks	✓ P	assed
Center AC Vent	✓ P	assed
Front Right AC Vent	✓ P	assed
Heater	✓ P	assed
Rear Blower Switch	✓ P	assed
Rear Left AC Vent	✓ P	assed
Parking Sensors	✓ P	assed
Rear Defogger	✓ P	assed
USB Charging Port	✓ P	assed
Power/ Manual Windows	✓ P	assed

Left Front Alloy/ Rim	✓ Passed
Left Rear Alloy/ Rim	✓ Passed
Right Front Alloy/ Rim	✓ Passed
Right Rear Alloy/ Rim	✓ Passed
Spare Alloy/ Rim Condition	✓ Passed
Wheel cover	✓ Passed
Antenna	✓ Passed
Prill Condition	✓ Passed
Monogram	✓ Passed
Nindow Glass	✓ Passed
Niper	✓ Passed
Panel Condition	
Rear Trunk Panel	✓ Passed

teering	
Steering wheel	✓ Passed
rake System	
Parking Brake	✓ Passed
Brake Master Cylinder	✓ Passed
Brake Disc & Brake Pad	✓ Passed
Brake Fluid	✓ Passed
uspension	
Shock Absorbers	✓ Passed

📠 Interiors & Luggage	
Dashboard And Instrument Panel	✓ Passed
Central Console	✓ Passed
Cup Holder	✓ Passed
Glove Box	✓ Passed
Steering Wheel	✓ Passed

Left Hand Side Front Tyre	✓ Passed
Left Hand Side Rear Tyre	✓ Passed
Right Hand Side Front Tyre	✓ Passed
Right Hand Side Rear Tyre	✓ Passed
Spare Tyre	✓ Passed
	✓ <75%
ife remaining  LHS Front Tyre  LHS Rear Tyre	•
LHS Front Tyre	<75% <75% <75%
LHS Front Tyre  LHS Rear Tyre	✓ <75%